

NY,
EAST-HAMPTON,
7

Key to Photographs

W. Y.	Dominy House (1715)
52 - Hamte	East Hampton, L. I.
8	Suffolk Co.
	New York

- 1 Exterior, general view from southeast (clock shop at left).
July 20, 1940. Photos by Stanley P. Nixon.
- 2 Exterior, general view from north east (carpenter shop
at right).
- 3 Exterior, view of rear from north west, showing later
additions.
- 4 Interior, view of parlor, showing fireplace wall.
- 5 Interior, view of east wall of kitchen.
- 6 Interior of carpenter shop. View from north end.
- 7 Interior of clock shop, showing east and south sides.
- 8 Interior of clock shop. View from east.
- 9 Interior of clock shop forge. View from north.
- 10 Interior, kitchen attic, showing door and cross bracing.